



MANUFACTURER

Portwest Limited, Westport, Co Mayo, Ireland

www.portwest.com/declarations

EN 1150:1999

Name and Address of Certified Body:

SATRA Technology Centre, Wyndham Way, Telford Way, Kettering,
Northamptonshire, NN16 8SD, UK. Notified Body Number: **NO:0321**

SATRA TECHNOLOGY EUROPE LTD,

Bracetown Business Park, Clonee, Dublin 15 D15 YN2P Ireland

Notified Body Number:2777

EN JUNIOR HIGH VISIBILITY CLOTHING

Refer to the product label for detailed information on the corresponding standards. Only standards and icons that appear on both the product and the user information below are applicable. All these products comply with the requirements of Regulation (EU 2016/425).

Limitations of use

The garment should be worn fastened at all times to provide the correct level of protection as stated above.

Keep clean. Should the High Visibility properties of this garment become irrecoverably soiled or contaminated, replace with a new one. Should garments be altered or filtered with additional labels or logo's, it may no longer comply with the declared standard.

Storage

Do NOT store in places subject to direct strong sunlight. If the garment becomes wet allow to dry at room temperature before storing. This garment must be kept clean to remain effective. Replace immediately if permanently damaged, stained or faded.
















Aftercare

Refer to garment label for washcare instructions. The manufacturer will not accept liability for garments where care labels have been ignored, defaced or removed. Please refer to garment label for the number of wash cycles claimed. The stated maximum number of cleaning cycles is not the only factor related to the lifetime of the garment. The lifetime will also depend on usage, care, storage, etc. Garments should be discarded when the protective qualities no longer apply: eg, 1. Maximum number of washes is reached. 2. The material has been damaged either by fading or has been torn. 3. The reflective qualities of the tape have faded. 4. Garment is permanently soiled, cracked, burned or heavily abraded.

Wash care labels: Refer to garment label for corresponding washing details

Retroreflective tape and labels

Retroreflective tape or labels should not be ironed.

	Max temp 30°C, mild process		Do not tumble dry		Do not iron
	Max temp 40°C, mild process		Tumble dry low		Iron max 110°C
	Max temp 40°C, normal process		Tumble dry normal		Iron max 150°C
	Max temp 60°C, normal process		Line dry		Do not dry clean
	Do Not Bleach		Drip line dry		Professional dry clean

MAX 50x | Maximum 50 Washes

MAX 25x | Maximum 25 Washes

MAX 12x | Maximum 12 Washes

MAX 5x | Maximum 5 Washes