



Number: GZHT90844514

Applicant: Date: Nov 23, 2018

Sample Description:

Eleven and a half (11.5) pairs of submitted samples said to be Injection lace up safety ankle boots in Black.

EN ISO 20345:2011 Size UK 2, 8, 11, 16 Ref. No. LC1708

Insert Plate Steel plate Toe Cap Steel toe cap

Sole 17#PU/Rubber outsole

Upper Black leather Vamp Lining White nonwoven Black mesh lining Quarter Lining Tonque Black PU Synthetic Collar Black PU Synthetic Insole Anti static nonwovens Insock Black mesh+EVA

Manufacturer

Supplier

Country of Original China Previous Report Number

Date Received/Date Test Started: Nov 12, 2018

Date Final Information Confirmed/

Date Payment Received:

Test Result Please Refer To Attached Page(5).

Should you have any query on this report, you may contact at <a href="mailto:qzfootwear@intertek.com">qzfootwear@intertek.com</a>

Authorized By:

For Intertek Testing Services Shenzhen Ltd.

Guangzhou Branch

Huang Ning, Andy

Assistant General Manager

Page 1 Of 9

AW / lydiayang

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

China

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Calpin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路7号之二第1~8层02房、01房101、

中国广州经济技开发区开发大道 256 号恒诺大厦 5 楼

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

2201 . 2501 . E401 . 2601 . 2601 . 2701 . 2801

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730





Number: GZHT90844514

Specific Ergonomic Features (Whole Footwear) (EN ISO 20344:2011(5.1))

Sample	Size		Assessment	Requirement	Pass/Fail
-	2	Left	For Question 4, Kneeling / Crouching Down Was Not Performed Due To The Footwear Is Rigid In Accordance With ISO 20344,8.4.1. Except This, Other Answers Are Positive	*	Pass
		Right	For Question 4, Kneeling / Crouching Down Was Not Performed Due To The Footwear Is Rigid In Accordance With ISO 20344,8.4.1. Except This, Other Answers Are Positive	*	Pass
	8	Left	For Question 4, Kneeling / Crouching Down Was Not Performed Due To The Footwear Is Rigid In Accordance With ISO 20344,8.4.1. Except This, Other Answers Are Positive	*	Pass
		Right	For Question 4, Kneeling / Crouching Down Was Not Performed Due To The Footwear Is Rigid In Accordance With ISO 20344,8.4.1. Except This, Other Answers Are Positive	*	Pass
	11	Left	For Question 4, Kneeling / Crouching Down Was Not Performed Due To The Footwear Is Rigid In Accordance With ISO 20344,8.4.1. Except This, Other Answers Are Positive	*	Pass
		Right	For Question 4, Kneeling / Crouching Down Was Not Performed Due To The Footwear Is Rigid In Accordance With ISO 20344,8.4.1. Except This, Other Answers Are Positive	*	Pass

Remark: \* = All The Answers Are Positive In The Questionnaire As Below:

Question 1: Is The Inside Surface Of The Footwear Free From Rough, Sharp Or Hard Areas That Caused You Irritation Or Injury?

Question 2: Is The Footwear Free Of Features That You Consider To Make Wearing The Footwear Hazardous?

Question 3: Can The Fastening Be Adequately Adjusted (If Necessary)?

Question 4: Can The Following Activities Be Performed Without Problems?

4.1 Walking

4.2 Climbing Stairs

4.3 Kneeling/ Crouching Down (It Is Not Applicable If The Footwear Is Rigid In

Accordance With ISO 20344, 8.4.1.)

/ lydiayang

Page 2 Of 9

深圳天祥质量技术服务有限公司广州分公司

E201, E501, E401, E501, E601, E701, E001 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663





TEST REPORT
Tests Conducted (As Requested By The Applicant)

2 Construction (Whole Footwear) (EN ISO 20345:2011(5.3.1.1))

Sample	Size	Assessment	Requirement	Pass/Fail
	2	The Insole Cannot Be Removed Without Damaging The Footwear	*	Pass
-	8	The Insole Cannot Be Removed Without Damaging The Footwear	*	Pass
	16	The Insole Cannot Be Removed Without Damaging The Footwear	*	Pass

Remark: \* = The Insole Cannot Be Removed Without Damaging The Footwear.

If There Is No Insole, A Permanently Attached Insock Shall Be Present.

3 General (Toe Protection) (EN ISO 20345:2011(5.3.2.1))

Sample	Size	Assessment	Requirement	Pass/Fail	
	2	The Toecap Cannot Be Removed Without Dam Footwear. Edge Covering Beneath Toecap: Edge Covering Behind Toecap: Width Of Toecap Flange: The Scuff -Resistant Covering Is Not Present. Vamp Lining Present.	7 mm 11 mm 5 mm	*	Pass
-	8	The Toecap Cannot Be Removed Without Dam Footwear. Edge Covering Beneath Toecap: Edge Covering Behind Toecap: Width Of Toecap Flange: The Scuff -Resistant Covering Is Not Present. Vamp Lining Present.	7 mm 12 mm 5 mm	*	Pass
	16	The Toecap Cannot Be Removed Without Dam Footwear. Edge Covering Beneath Toecap: Edge Covering Behind Toecap: Width Of Toecap Flange: The Scuff -Resistant Covering Is Not Present. Vamp Lining Present.	6 mm 12 mm 6 mm	*	Pass

Remark: \* = The Toecap Cannot Be Removed Without Damaging The Footwear.

Edge Covering Beneath Toecap: Min. 5 mm
Edge Covering Behind Toecap: Min. 10 mm
Width Of Toecap Flange: Max. 10 mm
Thickness Of Scuff-Resistant Covering: Min. 1 mm

Footwear Shall Have A Vamp Lining Or An Element Of The Upper That Serves As A Lining.

Expanded Uncertainty:

Edge Covering Beneath Toecap: 0.29 mm, With k= 1.96 At 95% Confidence Level. Edge Covering Behind Toecap: 0.45 mm, With k= 2.1 At 95% Confidence Level. Width Of Toecap Flange: 0.45 mm, With k= 2.1 At 95% Confidence Level.

/ lydiayang

Page 3 Of 9

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、

E201, E501, E401, E501, E601, E701, E001 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663 China 中国广州经济技开发区开发大道 255 号恒运大厦 5 楼 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou



TEST REPORT



Tests Conducted (As Requested By The Applicant)



Number: GZHT90844514

Internal Length Of Toe Caps (Toe Protection) (EN ISO 20344:2011(5.3))

Sample	Size	Re	Requirement	Pass/Fail	
-	2	Left 36 mm		Min. 34 mm	Pass
		Right	36 mm	Min. 34 mm	Pass
	8	Left	40 mm	Min. 39 mm	Pass
		Right	41 mm	Min. 39 mm	Pass
	16	Left	44 mm	Min. 42 mm	Pass
		Right	43 mm	Min. 42 mm	Pass

Expanded Uncertainty: 0.89 mm, With k = 2.22 At 95% Confidence Level.

Impact Resistance Of Safety Footwear (EN ISO 20344:2011(5.4))

Test Condition:

Mass Of Striker:  $(20\pm0.2)$  kg  $(200\pm 4) J$ Impact Energy:

Sample	Size		Requirement	Pass/Fail	
-	2	Left 15.0 mm		Min. 12.5 mm (#)	Pass
		Right	18.0 mm	Min. 12.5 mm (#)	Pass
	8	Left	23.0 mm	Min. 14.0 mm (#)	Pass
		Right	22.5 mm	Min. 14.0 mm (#)	Pass
	16	Left	23.5 mm	Min. 15.0 mm (#)	Pass
		Right	23.0 mm	Min. 15.0 mm (#)	Pass

Remark: # = In Addition, The Toecap Shall Not Develop Any Cracks Which Go Through The Material, i.e. Through Which Light Can Be Seen.

Expanded Uncertainty: 0.36(Urel), With k=1.96 At 95% Confidence Level.

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730



中国认可 国际互认 检测 TESTING CNAS L0220

GZHT90844514

Number:

Total Quality. Assured. TEST\_REPORT

Tests Conducted (As Requested By The Applicant)

6 Compression Resistance Of Safety Footwear (EN ISO 20344:2011(5.5))

Test Condition:

Compression Speed:  $(5\pm 2)$  mm/min Load:  $(15\pm 0.1)$  kN

Sample	Size	Results		Requirement	Pass/Fail
-	2	Left	> 20.0 mm	Min. 12.5 mm	Pass
		Right	> 20.0 mm	Min. 12.5 mm	Pass
	8	Left	24.0 mm	Min. 14.0 mm	Pass
		Right	24.0 mm	Min. 14.0 mm	Pass
	16	Left	24.5 mm	Min. 15.0 mm	Pass
		Right	24.0 mm	Min. 15.0 mm	Pass

Expended Uncertainty: 0.13 mm, With k= 1.96 At 95% Confidence Level.

7 Penetration Resistance (Whole Footwear With Metallic Anti-penetration Insert) (EN ISO 20344:2011(5.8.2))

Sample	Size		Results	Requirement	Pass/Fail
-	2	Left	1255 N	Min. 1100 N	Pass
		Right	1203 N	Min. 1100 N	Pass
	8	Left	1227 N	Min. 1100 N	Pass
		Right	1239 N	Min. 1100 N	Pass
	16	Left	1221 N	Min. 1100 N	Pass
		Right	1248 N	Min. 1100 N	Pass

Expanded Uncertainty: 16.99 N, With k=2.26 At 95% Confidence Level.

8 Construction (Whole Footwear) EN ISO 20345:2011(6.2.1.2)

Sample	Size		Assessment	Requirement	Pass/Fail
-	2	Left	Comply With Requirement.	*	Pass
		Right	Comply With Requirement.	*	Pass
	8	Left	Comply With Requirement.	*	Pass
		Right	Comply With Requirement.	*	Pass
	16	Left	Comply With Requirement.	*	Pass
		Right	Comply With Requirement.	*	Pass

Remark:

The Penetration Resistance Insert Can Not Be Removed Without Damaging The Footwear. Except For Non-Metallic Inserts That Also Function As An Insole, The Insert Shall Not Lie Above The Flange Of The Safety Toecap And Shall Not Be Attached To It

China

/ lydiayang

Page 5 Of 9

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

E201、E501、E401、E501、E601、E701、E801 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663





Total Quality. Assured. TEST REPORT

Tests Conducted (As Requested By The Applicant)

9 Dimensions (Whole Footwear) (EN ISO 20344:2011(5.8.1))

Sample	Size		Results	Requirement	Pass/Fail
-	2	Left	Except The Heel Region: 6.5 mm In The Heel Region: 1 mm The Penetration-Resistant Insert Has No Holes.	*	Pass
		Right	Except The Heel Region: 5 mm In The Heel Region: 3 mm The Penetration-Resistant Insert Has No Holes.	*	Pass
	8	Left	Except The Heel Region: 5 mm In The Heel Region: 0 mm The Penetration-Resistant Insert Has No Holes.	*	Pass
		Right	Except The Heel Region: 5 mm In The Heel Region: 0 mm The Penetration-Resistant Insert Has No Holes.	*	Pass
	16	Left	Except The Heel Region: 5 mm In The Heel Region: 3 mm The Penetration-Resistant Insert Has No Holes.	*	Pass
		Right	Except The Heel Region: 4 mm In The Heel Region: 0 mm The Penetration-Resistant Insert Has No Holes.	*	Pass

Remark:

\* = The Distance Between The Line Represented By The Feather Edge Of The Last And The

Edge Of The Insert:

Except The Heel Region: Max. 6.5 mm In The Heel Region: Max. 17 mm

The Penetration-Resistant Insert Shall Have No More Than Three Holes With A Maximum Diameter Of 3 mm To Attach It To The Bottom Of Footwear. The Holes Shall Not Lie In

The Area Specified

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou





Total Quality. Assured. TEST REPORT

Tests Conducted (As Requested By The Applicant)

10 Antistatic Footwear (Electrical Resistance) (EN ISO 20344:2011(5.10))

## Test Conditions

Test condition.					
Condition:	Dry	Wet			
Temperature:	(20±2) ℃	(20±2) ℃			
Relative Humidity:	(30±5) %	(85±5) %			
Period:	7 Days				
Internal Electrode:	(4±1) kg Steel Balls	Of 5 mm Diameter			
Test Voltage:	(100±2	2) V DC			
Test Period:	1 Mir	nute			

Sample	Condition	Size		Results	Requirement	Pass/Fail
-		2	Left	64.8 MΩ	*	Pass
			Right	128.7 MΩ	*	Pass
		8	Left	238 ΜΩ	*	Pass
	Dry		Right	43.7 MΩ	*	Pass
		16	Left	32.3 MΩ	*	Pass
			Right	17.7 MΩ	*	Pass
		2	Left	3.93 MΩ	*	Pass
			Right	2.72 ΜΩ	*	Pass
		8	Left	3.37 MΩ	*	Pass
	Wet		Right	5.82 MΩ	*	Pass
		16	Left	4.73 MΩ	*	Pass
			Right	4.21 MΩ	*	Pass

Remark: Above 100 k $\Omega$  And Less Than Or Equal To 1000 M $\Omega$ 

Expanded Uncertainty: 1.13 MΩ, With k= 2.06 At 95% Confidence Level.

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663





Number: GZHT90844514

Tests Conducted (As Requested By The Applicant)

11 Energy Absorption Of Seat Region (Whole Footwear) (EN ISO 20344:2011(5.14))

Sample	Size		Results	Requirement	Pass/Fail
-	2	Left 24 Joules		Min. 20 Joules	Pass
1 1		Right	24 Joules	Min. 20 Joules	Pass
1 1	8	Left	24 Joules	Min. 20 Joules	Pass
1 1		Right	25 Joules	Min. 20 Joules	Pass
	16	Left	28 Joules	Min. 20 Joules	Pass
1		Right	27 Joules	Min. 20 Joules	Pass

Expanded Uncertainty: 0.26 Joule, With k=2.11 At 95% Confidence Level.

12 Rigidity Test (Outsole) (EN ISO 20344:2011(8.4))

Sample	Size	Result
-	8	24°

Conclusion: There's No Need To Be Performed The Flexing Test.

NOTE Footwear Whose Angle Under The Applied Force Is Lower Than 45° From The Horizontal Is Not Subjected To The Flexing Test.

/ lydiayang

Page 8 Of 9

China

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730





Number:

GZHT90844514



End Of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report/except for full text copy) shall be made without the written approval by Intertek.

/ lydiayang

Page 9 Of 9

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Calpin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩线路 7 号之二第 1 一0 层 02 房、01 房 101、

E201, E501, E401, E501, E601, E701, E801

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510563

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, China

中国广州经济技开发区开发大道 255 号恒运大厦 5 楼 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730